



ARMORED
KOMODO
HEAVY INDUSTRIES

LIQUID MASK: ALTERNATE STRIPPING METHOD

This is an alternative method in stripping / removing cured liquid mask on surfaces.



Apply liquid mask to desired areas and let dry.


*You can apply thin layers for this method.



Paint and let dry, then dip the parts on water.
Give it time for the liquid mask to re-activate.



*The bigger the area masked, the longer it should be dipped.




Once reactivated, you can start removing
the liquid mask with a soft brush.

**this can be done with minimum force



RESULTS





Once reactivated, you can start removing
the liquid mask with a soft brush.

**This can be done with minimum force.



ARMORED
KOMODO
HEAVY INDUSTRIES