

# AIRBRUSH CLEANING TIPS



ARMORED  
KOMODO  
HEAVY INDUSTRIES





# USE LATEX GLOVES

Cleaning chemicals are often harsh to the skin. strip off paint residues, not your skin.



ARMORED  
KOMODO  
HEAVY INDUSTRIES



## **APPLICABLE FOR DURING AND END OF PAINT SESSIONS:**

After paint layers, pour airbrush cleaning fluids to instantly remove left over paint.



**ARMORED  
KOMODO**  
HEAVY INDUSTRIES



Clean the cup more easily by using an old brush to reach tight areas.

\*Cleaning your airbrush every paint session is easier compared to deep cleaning every after project



**ARMORED  
KOMODO**  
HEAVY INDUSTRIES



Besides working on a well ventilated room/area, use airbrush cleaning pots to greatly reduce fumes from cleanup.



**ARMORED  
KOMODO**  
HEAVY INDUSTRIES



# DEEP CLEANING:

Take a plastic container and fill it halfway with lacquer/acrylic thinner/pure acetone to remove leftover paint that possibly clog or stick on unwanted surfaces.

stronger cleaning solutions should take less time in removing debris, thus shorter submerged time for your airbrush is required as it may damage parts [and or o-rings]

brush off paint leftovers for faster cleaning.

Optional: use an ultrasonic cleaner.



ARMORED  
KOMODO  
HEAVY INDUSTRIES



## DISASSEMBLY:

If it is your first time disassembling an airbrush, take photos of every piece you remove.




Sometimes disassembly is required to clean your airbrush further. As parts itself may block or hinder the removal of debris.



**ARMORED**  
**KOMODO**  
HEAVY INDUSTRIES



# RE-ASSEMBLY:



Since the nozzle is removed, insert the needle [flat end] inwards the nozzle. This is done to avoid bending the tip  
(**WHICH IS EXTREMELY FRAGILE**)



**ARMORED  
KOMODO**  
HEAVY INDUSTRIES



## RE-ASSEMBLY:

Return the nozzle with MINIMAL force. Use the wrench provided to SLIGHTLY tighten. again, MINIMAL force from the wrench is required, as the nozzle is easy to break from over tightening.



**ARMORED  
KOMODO**  
HEAVY INDUSTRIES